

锂离子电池技术规格书

Lithium-ion Battery Pack Datasheet

电池组型号/Battery Pack Model: 16S1P-51.2V_100Ah

料号/Part Number: 91410151

客户承认章		公司承认章		研发部	
Customer Approval Stamp		Company Approval Stamp		Research and Development Department	
部门 DEPT.		部门 DEPT.		版本 Version	A/0
				最新生效 日期	2023-05-09
				Latest Effective Date	
				页数	32
				Page	
				编制 Prepared by	陈锦洲 Chen, Jinzhou
				审核 Reviewed by	
生效日期 Effective Date		生效日期 Effective Date	2023-05-09	批准 Approved by	



	版本变更履历表			
	Version Change History Table			
版本编号 Version No.	主要变更履历描述 Main Change Description	编制人 Prepared by	生效日期 Effective Date	
A/0	首次发行	陈锦洲	2023-05-09	
	Initial Release	Chen, Jinzhou		



目录

1	范围/S	Scope	4
2	测试象	条件/Test Conditions	4
	2.1	测试环境条件/Test Environment Conditions	4
	2.2	测量仪表与设备要求/Measurement Instrument and Equipment Requirements	4
3	成品/F	Final Product	5
	3.1	主要技术参数/Key Technical Parameters	5
	3.2	常规性能/Conventional Performance	6
	3.3	安全性能/Safety Performance	8
	3.4	环境适应性/Environmental Adaptability	. 13
4	零部件	F/Components	. 14
	4.1	电芯/Battery Cells	. 14
	4.1.1	电池性能/Battery Performance	. 15
	4.1.2	安全性能/Safety Performance	. 19
	4.2	保护板参数/Protection Board Parameters	. 19
	4.2.1	环境要求/Environmental Requirements	. 19
	4.2.2	电气特性/Electrical Characteristics	. 20
	4.2.3	LED指示说明/LED Indication Instructions	. 26
5	包装、	储存、运输/Packaging, Storage, and Transportation	. 28
	5.1	包装/Packaging	. 28
	5.2	储存/Storage	. 29
	5.3	运输/Transportation	. 29
6	成品尺	只寸及接口说明/Product Dimensions and Interface Description	. 30
7	使用说	拍明与注意事项/Instructions and Precautions	. 30
	7.1	使用说明/Instructions	. 30
	7.2	注意事项/Precautions	. 31
	7.3	警告/Warning	. 32



1 范围/Scope

本规格书描述本公司设计开发的锂离子电池产品,它是产品生产和检验的依据,以及让顾客了解产品的规格参数及正确使用方法。

This specification document describes the lithium-ion battery products designed and developed by our company. It serves as a reference for product manufacturing and testing, as well as to provide customers with information about the product's specifications and proper usage methods.

2 测试条件/Test Conditions

2.1 测试环境条件/Test Environment Conditions

除非另有规定,本规格书中各项试验应在标准大气条件下进行:

温度: 15℃~35℃

相对湿度: 45%~75%

大气压力: 86kPa~106kPa

Unless otherwise specified, all tests mentioned in this specification document should be conducted under standard atmospheric conditions, which include the following ranges:

Temperature: 15°C to 35°C

Relative Humidity: 45% to 75%

Atmospheric Pressure: 86 kPa to 106 kPa

2.2 测量仪表与设备要求/Measurement Instrument and Equipment Requirements

- 2.2.1 测量电压的仪表精度应不低于 0.5 级,内阻应不小于 10KΩN。
- 2.2.2 测量电流的仪表精度应不低于 0.5 级。
- 2.2.3 测量时间的仪表准确度应不低于±0.1%。
- 2.2.4 测量温度的仪表准确度应不低于±0.5℃。
- 2.2.1 The instrument accuracy for voltage measurement should not be lower than level 0.5, and the internal resistance should not be less than $10K\Omega/V$.
- 2.2.2 The instrument accuracy for current measurement should not be lower than level 0.5.
- 2.2.3 The instrument accuracy for time measurement should not be lower than $\pm 0.1\%$.
- 2.2.4 The instrument accuracy for temperature measurement should not be lower than ±0.5°C.



3 成品/Final Product

3.1 主要技术参数/Key Technical Parameters

项目	参数	备注
Item	Parameter	Remarks
额定容量	100Ah	0.5C 放电
Rated Capactiy		0.5C Discharge
最小容量	98.8Ah	
Minimum Capacity		
额定电压	51.2V	
Rated Voltage		
内阻	.05.0	AC 1kHz 交流测
Internal Resistance	≤0.5mΩ	AC 1kHz AC Measurement
		内阻
		Internal Resistance
组合方式	16S1P	
Assemble Method		
充电方式	CC/CV	恒流转恒压 Constant Current to Constant
Charging Method		Voltage
标准充电电流	0.2C	
Standard Charging		
Current		
最大充电电流	≤100A	
Maximum Charging Current		
标准放电电流	0.2C	
Standard Discharge Current		
最大放电电流	≤100A	
Maximum Discharge Current		
充电限制电压	51.2V	
Charging Voltage Limit		
放电截止电压	10V	
Discharge Cut-off Voltage		



出厂电压	48V~51.2V	
Factory Voltage		
重量	约43.81kg	
Weight	Approximately 43.81 kg	
充电温度	0°C∼+45°C	
Charging Temperature		
放电温度	−20°C∼ +	
Discharging Temperature	60°C	
	1 个月:-20~60℃	
储存温度	1 month: -20~60°C	
Storage Temperature	3 个月: -10~40°C 3 months: -10~40°C	
	1年: -5~20℃ 1 year: -5~20℃	
相对湿度	45%~85% RH	
Relative Humidity		

3.2 常规性能/Conventional Performance

项目	测试方法	判定标准
Item	Test Method	Criteria
标准充电 Standard Charging	Test Method 在环境温度为(25±2)°C条件下,用 0.2C 电流对电池充电,当电压到充电限制压时,改为充电限制压恒压充电,直到充电电流小于 0.02C 停止充电。 Under ambient temperature conditions of (25+2)°C, charge the battery with a current of 0.2C until the voltage reaches the charging limited voltage. Then switch to constant voltage charging until the charging current drops below 0.02C, at which point charging should be stopped.	充电时间≤8h Charging time ≤ 8 hours.



额定容量 Rated Capacity	在环境温度为(25±2)°C条件下,以标准充电方式充满后,搁置 0.5h, 0.2C 放电至放电截止电压,记录放电容量。 Under ambient temperature conditions of (25±2)°C, fully charge the battery using the standard charging method, then let it stand for 0.5 hours. Discharge the battery with a current of 0.2C until the discharge cut-off voltage is reached, and record the discharge capacity.	≥最小容量 ≥Minimum capacity
内阻 Internal Resistance 荷电保持能力 Charge Retention Capacity	使用AC 1kHz 检测方法 Use the AC 1kHz testing method. 电池标准充电结束后,在环境温度为 (25±2)℃条件下,将电池开路搁置 28 天, 0.2C 放电至放电截止电压 V,记录放电容量。 After the battery has completed the standard charging process, let it stand for 28 days at ambient temperature conditions of (25±2)℃. Discharge the battery with a current of 0.2C until the discharge cut-off voltage V is reached, and record the discharge capacity.	参见3.1内阻项 Refer to 3.1 for Internal Resistance ≥初始容量的 85% ≥ 85% of the initial capacity.
循环寿命 Cycle Life	在环境温度为(25±2)°C的条件下,以标准充电方式充满后,搁置 0.5h,然后以电流 0.2C恒流放电到放电截止电压,放电结束后,搁置 0.5h,再进行下一个充放电循环,直至连续两次额定容量≤80%。 Under the condition of ambient temperature (25±2)°C, the battery is fully charged using the standard charging method, followed by a 0.5-hour rest period. Then, it is discharged at a constant current of 0.2C until the discharge cut-off voltage is reached. After the discharge, a 0.5-hour rest period is observed before starting the next charge and discharge cycle. This process is repeated until the rated capacity reaches or falls below 80% for two consecutive cycles.	循环次数≥6000次 Number of cycles: ≥6000 times



3.3 安全性能/Safety Performance

项目	测试方法	 判定标准
Item	Test Method	Criteria
常温外部短路 Ambient Temperature External Short Circuit	电池充满电后,放置在温度为 25°C±2°C的条件下,待电池温度达到 25°C±2°C时,在放置 30min,在用导线连接电池正负极端,并确保全部 外部电阻为 80±20 毫欧,(导线的电阻率温度系数小于5*10 ⁻³ /°C)当 出现以下两种情形,实验终止:a)电池温度下降到比峰值低 20%,b)短接时间达到24H。 After fully charging the battery, place it in a temperature-controlled environment at 25°C±2°C. Once the battery temperature reaches 25°C±2°C, let it rest for 30 minutes. Then, connect the battery terminals with a wire, ensuring that the total external resistance is 80±20 milliohms (with a wire resistance temperature coefficient less than 5*10-3/°C). The experiment will be terminated under the following conditions: a) If the battery temperature drops by 20% compared to the peak value, or b) If the short-circuit time reaches 24 hours.	电池应不爆炸、 不起火、最高温度不超过 150℃ The battery should not explode, catch fire, or exceed a maximum temperature of 150℃.
高温外部短路 High Temperature External Short Circuit	电池充满电后,放置在温度为 55°C±5°C的条件下,待电池温度达到 55°C±5°C时,在放置 30min,在用导线连接电池正负极端,并确保全部 外部电阻为 80±20 毫欧,(导线的电阻率温度系数小于5*10 ⁻³ /°C)当 出现以下两种情形,实验终止:a)电池温度下降到比峰值低 20%,b)短接时间达到24H。 After fully charging the battery, place it in a temperature-controlled environment at 55°C±5°C. Once the battery temperature reaches 55°C±5°C, let it rest for 30 minutes. Then, connect the battery terminals with a wire, ensuring that the total external resistance is 80±20 milliohms (with a wire resistance temperature coefficient less than 5*10-3/°C). The experiment will be terminated under the following conditions: a) If the battery temperature drops by 20% compared to the peak value, or b) If the short-circuit time reaches 24 hours.	电池应不爆炸、不起火、最高温度不超过 150℃ The battery should not explode, catch fire, or exceed a maximum temperature of 150℃.



燃烧喷射 Fire Jetting	电池充满电后,将电池放置在实验工装的钢丝网上,需用单根金属丝固 定样品电池在钢丝网上,用火焰加热电池,当出现以下三种情况可停止加热: a)电池爆炸; b)电池完全燃烧; c)持续加热30min,电池未起火、未爆炸。 After fully charging the battery, place it on a wire mesh in the experimental fixture. Secure the sample battery to the wire mesh using a single metal wire. Heat the battery using a flame. The heating process can be stopped under the following three conditions: a) Battery explosion, b) Complete combustion of the battery, or c) Continuous heating for 30 minutes without the battery catching fire or exploding.	组成的电池的部件 (粉尘状产物除 外)或电池产物不 得穿透铝网 Components of the battery (excluding dust-like substances) or battery products should not penetrate the aluminum mesh.
过充电 Overcharging	单体电芯(不含保护板电路),在 25°C±2°C的环境温度下以 0.2C恒流放电至终止电压,然后设置恒流电流为 3C、电压为 3.65V,直至电压达到最大值后,电池持续充电时间达到 7小时,电池温度下降到比峰值低20%。 For an individual cell (excluding the protection circuit), discharge it at a constant current of 0.2C to the termination voltage at a temperature of 25°C±2°C. Then, set the constant current to 3C and the voltage to 3.65V. Continue charging until the voltage reaches its maximum value. The battery should be continuously charged for 7 hours until the temperature drops by 20% compared to the peak value.	电池应不爆炸、 不起火 The battery should not explode or catch fire.
加速度冲击 Acceleration Shock	电池充满电后,固定在冲击台上,进行半正弦脉冲冲击实验,在最初的 3ms 内,最小平均加速度为 75gm,峰值加速度为 150±25gm,脉冲持续 时间为 6ms±1ms,电池三个相互垂直的方向依次进行三次加速度冲击。 After fully charging the battery, fix it on an impact table and perform a half-sine pulse shock test. Within the first 3ms, the minimum average acceleration should be 75gm, and the peak acceleration should be 150±25gm. The pulse duration should be 6ms±1ms. Repeat the acceleration shock test three times in three mutually perpendicular directions of the battery.	电池应不爆炸、不起火、不破裂、不冒烟、不漏液和不泄气 The battery should not explode, catch fire, rupture, smoke, leak liquid, or release gas.



热滥用 Thermal Abuse	电池冲满电后放置于热箱中,温度以(5°C±2°C)/min 的速率升至 130°C±2°C并保温 30min。 After fully charging the battery, place it in a thermal chamber and gradually raise the temperature to 130°C±2°C at a rate of (5°C±2°C)/min. Maintain the temperature for 30 minutes.	电池应不爆炸、 不起火 The battery should not explode or catch fire.
温度循环 Temperature Cycling	电池按标准充电充满电后,将电池放置在温度为 (25±2)°C的温控箱体中进行如下步骤,(1)将样品 放入温度为 75°C±2°C的实验箱中保持 6H; (2)将实验箱温度降为-40°C±2°C变保持 6H; (3)以上几种温度的转换时间不超过 30min; (4)重复步骤 1-2,共循环10次。 After fully charging the battery according to the standard charging procedure, place the battery in a temperature-controlled chamber at a temperature of (25±2)°C and perform the following steps: (1) Keep the sample in an experimental chamber at a temperature of 75°C±2°C for 6 hours, (2) Lower the temperature of the chamber to -40°C±2°C and keep it for 6 hours, (3) The transition time between different temperatures should not exceed 30 minutes, (4) Repeat steps 1-2 for a total of 10 cycles.	电池不泄漏、不 泄气不爆炸、不 起火和不破裂 The battery should not leak, release gas, explode, or catch fire.
强制放电 Forced Discharge	在环境温度为(25±2)℃条件下,电池以 0.2C进行放电至终止电压,然后以1C的电流对电池进行反向充电,要求充电时间不低于90min。 Under the condition of (25±2)℃ ambient temperature, discharge the battery at a rate of 0.2C until it reaches the termination voltage. Then, reverse charge the battery at a current of 1C, ensuring that the charging time is not less than 90 minutes.	电池应不起火和 不爆炸 The battery should not catch fire or explode.



过压充电 Overvoltage Charging	电池充满电后,继续以最大充电电流恒流充电至n*6.0V或者可以承受的最高电压值(两者取较高者),并保持该电压进行恒压充电。对于移除保护电路或是没有保护电路的电池充电1H,对于有保护电路的电池充电至保护板电路动作。 After fully charging the battery, continue charging it at the maximum charging current until it reaches either n*6.0V or the maximum permissible voltage (whichever is higher), and maintain that voltage for constant voltage charging. For batteries without protection circuits or with removed protection circuits, charge for 1 hour. For batteries with protection circuits, charge until the protection circuit activates.	电池不泄漏、 不泄气、不爆 炸、不起火和 不破裂 The battery should not leak, release gas, explode, or catch fire.
过流充电	电池放完电后,然后以1.5倍的过流充电保护电流(1.5C)进行恒流充电,对于移除保护电路或是没有保护电路的电池充电至上限电压,对于有保护电路的电池充电至保护板电路动作。	电池不泄漏、不 泄气不爆炸、不 起火和不破裂
Overcurrent Charging	After discharging the battery, perform a constant current charge at 1.5 times the overcurrent charging protection current (1.5C). For batteries without protection circuits or with removed protection circuits, charge until reaching the upper limit voltage. For batteries with protection circuits, charge until the protection circuit activates.	The battery should not leak, release gas, explode, or catch fire.
欠压放电	电池充满电后,以其最大放电电流恒流放电,对与移除保护电路或是没有保护电路的电池放电至(n*0.15)V,对与有保护电路的电池充电至保护板电路动作。放电后静置10min,并继续按标准充满电。	电池不泄漏、不 泄气不爆炸、不 起火和不破裂
Under-voltage Discharge	After fully charging the battery, discharge it at a constant current equal to its maximum discharge current. For batteries without protection circuits or with removed protection circuits, discharge until reaching (n*0.15)V. For batteries with protection circuits, discharge until the protection circuit activates. After the discharge, let the battery rest for 10 minutes and then continue with the standard full charging procedure.	The battery should not leak, release gas, explode, or catch fire.



4++:	电池充满电后,然后以 1.5 倍的过流放电保护电流 (1.5C)进行恒流 放电,对与移除保护电路或是没 有保护电路的电池放电至放电截止电 压,对与有 保护电路的电池充电至保护板电路动作。	电池不泄漏、不 泄气不爆炸、不 起火和不破裂
过载 Overload	After fully charging the battery, perform a constant current discharge at 1.5 times the overcurrent discharge protection current (1.5C). For batteries without protection circuits or with removed protection circuits, discharge until reaching the discharge cutoff voltage. For batteries with protection circuits, discharge until the protection circuit activates.	The battery should not leak, release gas, explode, or catch fire



3.4 环境适应性/Environmental Adaptability

项目	测试方法	判定标准
		Critera
Item	Test Method 将满电的样品放在高温实验箱中,实验箱中的温度设	Critera
高温使用 High- temperature usage	为电池规定的充电 上限温度和放电上限温度,电池的充电和放电的上限温度及 80°C中的 最大值,待电池表面温度稳定后,保持 7H。 Place the fully charged samples in a high-temperature test chamber, setting the temperature in the chamber to the upper limit for charging and discharging specified for the battery, as well as the maximum value within 80°C. After the surface temperature of the battery stabilizes, keep it for 7 hours.	切断电源,电池 应不爆炸、不起 火和不漏液 Cut off the power supply, the battery should not explode, catch fire, or leak.
振动 Vibration	电池充满电后,将电池或电池组变形,采用正弦波进行振动,并以对数扫频方式在 15min 内从 7Hz 扫频到 200Hz 并返回 到 7Hz。振动沿样品互相垂直的 3 个方向(其中一个方向必须与样品正负极所在平面垂直)进行,每个方向按上述对数扫频方式重复 12 次,振动 3h。对数扫频方式 如下: 7Hz-18Hz 保持 9.8m/s² 的峰值加速度,将振幅保持在0.8mm(位移为 1.6mm)直至峰值加速度达到 78.4m/s²(频率约为 50Hz)。保持78.4m/s²的峰值加速度直到频率增长到 200Hz。实验后在对电池进行一次充放电循环。 After the battery is fully charged, fix the battery or battery pack on the vibration table without causing any deformation. Use a sine wave for vibration and perform logarithmic sweep frequency from 7Hz to 200Hz within 15 minutes and return to 7Hz. The vibration is conducted in three directions perpendicular to each other (one of which must be perpendicular to the plane where the positive and negative terminals of the sample are located), repeating the logarithmic sweep frequency method 12 times in each direction. The vibration lasts for 3 hours. The logarithmic sweep frequency method is as follows: from 7Hz to 18Hz, maintain a peak acceleration of 9.8m/s² while keeping the amplitude at 0.8mm (displacement of 1.6mm) until the peak acceleration reaches 78.4m/s² (at a frequency of approximately 50Hz). Maintain the peak acceleration of 78.4m/s² until the frequency increases to 200Hz. After the experiment, perform one charge-discharge cycle on the battery.	电池不泄漏、不破裂 不起火和不爆炸 The battery should not leak, rupture, catch fire, or explode.



自由跌落 Free Fall	充电结束后,搁置 1-4H 后进行测试。将电池样品由高度为 1000mm 的位置自由跌落到置于混凝土板上,从 X、Y、 Z 正负方向(六个方向)每个方向自由跌落 1 次。(1000mAh 以上的高度1000MM,1000mAh以下的1500MM)。 After the charging is completed, let the battery rest for 1-4 hours before conducting the test. Release the battery sample freely from a height of 1000mm and let it fall onto a concrete plate, performing one free fall in each of the positive and negative directions of X, Y, and Z axes (six directions in total). (For batteries with a capacity of 1000mAh or higher, the height of the free fall is 1000mm, while for batteries with a capacity below 1000mAh, the height is 1500mm).	不泄漏,不 起火和不爆 炸 No leakage, no fire, and no explosion.
低气压 Low Pressure	电池快速充电或标准充电后,将样品搁置在 (25±2)℃真空箱中,真空箱密闭后,逐渐减少其 内部压力至不高于 11.6kPa(模拟海拔 15240m) 并保 持 6H。 After rapid charging or standard charging, place the sample in a (25±2)℃ vacuum chamber. Once the vacuum chamber is sealed, gradually reduce the internal pressure to no higher than 11.6kPa (simulating an altitude of 15240m) and keep it for 6 hours.	电池应不泄 漏,不泄 气、不破裂 不起火和不 爆 炸 The battery should not leak, vent, rupture, catch fire, or explode.

4 零部件/Components

4.1 电芯/Battery Cells

生产厂家 Manufacturer	湖北亿纬动力有限公司 Hubei EVE Power Co., Ltd.	型号 Model	LF100 LA
额定容量 Rated Capacity	100Ah	额定电压 Rated Voltage	3.2V
内阻 Internal Resistance	≤0.5mΩ	充电上限电压 Charging Max Voltage	3.65V
重量 Weight	约1.98KG Approximately 1.98 kg	放电截止电压 Discharge Cut- off Voltage	2.5V



4.1.1 电池性能/Battery Performance

序号	项目	技术要求	测试方法
Number	Item	Technical Requirements	Test Method
1	25°C倍率放 电性能 Discharge Performance Rate at 25°C	放电容量/标称容量× 100% A) 0.5C(A)≥100% B) 1C(A)≥98% Discharge capacity/Nominal capacity× 100% A) 0.5C(A)≥100% B) 1C(A)≥98%	电池标准充电后,搁置0.5h,分别以0.5C (A)、1C(A)进行放电至2.5V,如果放电容量达不到技术要求,此项试验允许重复3次。 After standard charging the battery, let it stand for 0.5 hours, then discharge it to 2.5V at 0.5C (A) and 1C (A) respectively. If the discharge capacity does not meet the technical requirements, this test can be repeated up to 3 times.
2	不同溫度放 电性能 Discharge Performance at Different Temperatures	放电容量/标称容量× 100% A) 0.5C(A)≥95% B) 1C(A)≥70% Discharge capacity/Nominal capacity× 100% A) 0.5C(A)≥95% B) 1C(A)≥70%	A) 电池标准充电后,在 55±2°C条件下搁置4h,以 1.0C(A)放电至2.5V B) 电池标准充电后,在- 20±2°C条件下搁置4h,以 1.0C(A)放电至2.0V A) After standard charging the battery, let it stand for 4 hours at 55±2°C, then discharge it to 2.5V at 1.0C(A). B) After standard charging the battery, let it stand for 4 hours at -20±2°C, then discharge it to 2.0V at 1.0C(A).



3	25°C荷电保 持与恢复能 力 Capacity Retention and Recovery Performance at 25°C	容量保持率: 剩余容量/标称容量≥95%容量恢复率: 恢复容量/标称容量≥97 % Capacity Retention: Remaining Capacity / Nominal Capacity ≥ 95% Capacity Recovery: Recovered Capacity / Nominal Capacity ≥ 97%	1) 电芯标准 充电后, 25±2°C 下静置28天; 2) 存储结束后, 电芯在25°C 下以0.5C恒流放电至2.5V, 静置30min; 计算容量保持率; 3) 电芯在25±2°C下以0.5C恒流恒压充电至3.65V/0.05C截止, 静置30min; 4) 电芯在25°C下以0.5C恒流放电至2.5V, 静置30min。计算容量恢复率; 5) 3-4步容量恢复步骤允许重复3次。 1) After standard charging, the cell is kept at 25±2°C for 28 days. 2) After storage, the cell is discharged at a constant current of 0.5C to 2.5V at 25°C, and then left for 30 minutes. Calculate the capacity retention. 3) The cell is charged at a constant current of 0.5C and constant voltage of 3.65V/0.05C at 25±2°C, and then left for 30 minutes. 4) The cell is discharged at a constant current of 0.5C to 2.5V at 25°C, and then left for 30 minutes. 4) The cell is discharged at a constant current of 0.5C to 2.5V at 25°C, and then left for 30 minutes. 5) Steps 3 and 4 of capacity recovery can be repeated up to 3 times.
---	---	---	--



4	25°C循环寿 命	≥4000次 @1.0C/1.0C	(25±2)°C, 电池在200kgf 夹 具下: 以1.0C(A)恒流恒压充 电至3.65V, 截止电流 0.05C(A), 搁置30min, 以 1.0C(A)恒流放电至2.5V, 搁 置30min, 再进行下一循环至 容量衰减为标称容量的80% 止。
	25°C Cycle Life	≥4000 cycles @1.0C/1.0C	At (25±2)°C, the battery is placed under a 200kgf fixture: charged at a constant current and voltage of 1.0C(A) to 3.65V, with the current cutoff at 0.05C(A), left for 30 minutes, discharged at a constant current of 1.0C(A) to 2.5V, left for 30 minutes, and then proceeds to the next cycle until the capacity decay reaches 80% of the nominal capacity.
5	35°C循环寿 命 35°C Cycle Life	≥2800次 @ 1.0C/1.0C ≥2800 cycles @ 1.0C/1.0C	(35±2)°C, 电池在200kgf夹具下: 以1.0C(A)恒流恒压充电至3.65V, 截止电流0.05C(A), 搁置30min, 以1.0C(A)恒流放电至2.5V, 搁置30min, 再进行下一循环, 至容量衰减为标称容量的80%止。 At (35±2)°C, the battery is placed under a 200kgf fixture: charged at a constant current and voltage of 1.0C(A) to 3.65V, with the current cutoff at 0.05C(A), left for 30 minutes, discharged at a constant current of 1.0C(A) to 2.5V, left for 30 minutes, and then proceeds to the next cycle until the capacity decay reaches 80% of the nominal capacity.



6	45°C循环寿 命 45°C Cycle Life	≥1800次 @ 1.0C/1.0C ≥1800 cycles @ 1.0C/1.0C	下:以1.0C(A)恒流恒压充电至3.65V,截止电流0.05C(A),搁置30min,以1.0C(A)恒流放电至2.5V,搁置30min,再进行下一循环,至容量衰减为标称容量的80%止。 At (45±2)°C, the battery is placed under a 200kgf fixture: charged at a constant current and voltage of 1.0C(A) to 3.65V, with the current cutoff at 0.05C(A), left for 30 minutes, discharged at a constant current of 1.0C(A) to 2.5V, left for 30 minutes, and then proceeds to the next cycle until the capacity decay reaches 80% of the nominal capacity.
7	寿命终止管 理 End-of-life Management	容量/标称容量<70% Capacity/Nominal Capacity < 70%	电池使用过程中,超出寿命终止规定时应停止使用电池。 During battery usage, the battery should be discontinued if it exceeds the end-of-life termination criteria.



4.1.2 安全性能/Safety Performance

序号	项目	技术要求	测试方法
Number	Item	Technical Requirements	Test Method
1	过放电	不爆炸、不起火	
	Over-discharge	No explosion, no ignition	
2	过放电	不爆炸、不起火	
	Over-discharge	No explosion, no ignition	
3	短路	不爆炸、不起火	★ ★ CD / 2027 € 2010
	Short Circuit	No explosion, no ignition	参考: GB/T 36276-2018
4	跌落	不爆炸、不起火	《电力储能用锂离子电
	Falling	No explosion, no ignition	池》
5	加热	不爆炸、不起火	D-f CD/T 26276
	Heating	No explosion, no ignition	Reference: GB/T 36276-
6	挤压	不爆炸、不起火	2018 "Lithium-ion Batteries for Stationary Energy
	Compression	No explosion, no ignition	Storage"
7	低气压	不爆炸、不起火	Storage
	Low Pressure	No explosion, no ignition, no	
		leakage	
8	热失控	不爆炸、不起火	
	Thermal Runway	No explosion, no ignition	

4.2 保护板参数/Protection Board Parameters

4.2.1 环境要求/Environmental Requirements

项目		单位
Item	Parameter	Unit
工作温度		
Operating	-20 ~ 75	°C
Temperature		
储存温度		
Storage	-20 ~ 75	°C
Temperature		
工作湿度		
Operating	10 ~ 85	%RH
Humidity		
储存湿度		
Storage	10 ~ 85	\$RH
Humidity		



4.2.2 电气特性/Electrical Characteristics

• 基本参数设置(注: 以下参数除特殊注明以外, 25C环境温度下测试

序号 Number	扌 Ind	出厂默认 参 Factory Default Parameters	是否可设 Configurable	备注 Remarks	
		单体过充告警电压 Single-cell Overcharge Alarm Voltage	3600 mV	Yes	
	单体过充保护 Single-cell Overcharge	单体过充保护电压 Single-cell Overcharge Protection Voltage	3700 mV	Yes	
1	Protection	单体过充保护延时 Single-cell Overcharge Protection Delay Time	1.0S	Yes	
	单体过压保护解除	单体过充保护解除电压 Single-cell Overcharge Protection Release Voltage	3380 mV	Yes	
	Single-cell Overvoltage Protection Release	容量解除 Capacity Release	SOC < 96%	Yes	
		放电解除		追流>1A	
		Discharge Release 单体过放告警电压	Discharge	current > 1A	
	单体过放保护	Single-cell Overdischarge Warning Voltage	2800 mV	Yes	过放保护30秒后,仍无法恢
	Single-cell Overdischarge Protection	单体过放保护电压 Single-cell Overdischarge Protection Voltage	2700 mV	Yes	复时,将进入 低功耗模式
2		单体过放保护延时 Single-cell Overdischarge Protection Delay Time	1.0S	Yes	If the over- discharge protection
	单体过放保护解除 Single-cell	单体过放保护解除电压 Single-cell Overdischarge Protection Release Voltage	2950 mV	Yes	cannot be restored after 30 seconds, it
	Overdischarge Protection Release	有充电时解除 Release when Charging	Activates w	已器可激活 hen connected charger	will enter low- power mode.



		总体过充告警电压 Total Overcharge Warning	57.6V	Yes	
	总体过充保护 Total Overcharge Protection	Voltage 总体过充保护电压 Total Overcharge Protection Voltage	58.4V	Yes	
3	Trocedon	总体过充保护延时 Total Overcharge Protection Delay Time	1.08	Yes	
	总体过压保护解除	总体过充保护解除电压 Total Overcharge Protection Release Voltage	54V	Yes	
	Total Overvoltage Protection Release	容量解除 Capacity Release 放电解除	SOC < 96% 放电电	Yes 流>1A	
		Discharge Release	Discharge c		
		总体过放告警电压 Total Over-discharge Warning Voltage	44.8V	Yes	过放保护30 秒后, 仍无法
	总体过放保护 Total Over- discharge Protection	总体过放保护电压 Total Over-discharge Protection Voltage	43.2V	Yes	恢复时,将进入低功耗模式
4		总体过放保护延时 Total Over-discharge Protection Delay Time	1.0S	Yes	If the over- discharge protection
	总体过放保护解除	总体过放保护解除电压 Total Over-discharge Protection Release Voltage	47.2V	Yes	cannot be restored after 30 seconds, it
	Total Over- discharge Protection Release	有充电时解除 Release during Charging		器可激活 en connected harger	will enter low-power mode.
	充电限流功能	充电限流电流			限流开启可 设置,最大开 启电流值 100A
5	Charging Current Limiting Function	5 Charging Current Charging Current Limit	20)A	Limit setting is adjustable, with a maximum current limit of 100A



		充电过流告警电流	105A	Yes	左续山顶10
	→ L _\\> /H L\	Charging Overcurrent Alarm Current	103A	1 es	连续出现10 次将锁定该
	充电过流保护 Charging Overcurrent	充电过流保护电流 Charging Overcurrent Protection Current	110A	Yes	状态,不再自 动解除
6	Protection	充电过流保护延时 Charging Overcurrent Protection Delay Time	1.0S	Yes	If it occurs continuously for 10 times,
	充电过流保护解除 Charging Overcurrent Protection Release	自动解除 Automatic Release	Automatic r	自动解除 elease after 1 nute	the state will be locked and no longer automatically released.
		放电解除 Discharge Release		流>1A current > 1A	
	放电过流1保护	放电过流1告警电流 Discharge Overcurrent 1 Warning Current	105A	Yes	连续出现10
	Discharge Overcurrent 1 Protection	放电过流1保护电流 Discharge Overcurrent 1 Protection Current	110A	Yes	状态, 不再自 动解除
7		放电过流1保护延时 Discharge Overcurrent 1 protection Delay Time	1.0S	Yes	If it occurs continuously for 10 times,
	放电过流1保护解 除 Discharge Overcurrent 1	自动解除 Automatic Release	1min 后自动解除 Automatic release after 1 minute		the state will be locked and no longer automatically released.
	Protection Release	放电解除 Discharge Release		流>1A current > 1A	
	放电过流2 Discharge	放电过流2保护电流 Discharge Overcurrent 2 Protection Current	≥150A	Yes	连续出现10 次将锁定该
	Overcurrent 2	放电过流2保护延时 Discharge Overcurrent 2 protection Delay Time	100 mS	Yes	状态,不再自动解除
8	放电过流2保护解 除 Discharge Overcurrent 2 Protection Release	自动解除 Automatic Release	Automatic r	自动解除 elease after 1 nute	If it occurs continuously for 10 times, the state will be locked and no longer automatically released.
		放电解除 Discharge Release		流>1A current > 1A	



		k= □ k □ □ L → L △ k		<i>-</i>	
		短路保护功能		有	
		Short Circuit Protection	Y	l'es	
	t → nh t → 1.5.	Function			
	短路保护		有充电时,知	逗路保护解除	
9	Short Circuit	短路保护解除	Short circu	it protection	
	Protection	Short Circuit Protection	release wh	nen charging	
		Release	负载移除后	,将自动解除	
			Automatic	release after	
			load r	removal	
		MOS 过温告警温度			
		MOS Over-heating	90°C	Yes	
	MOS 高温保护	Warning Temperature			
	MOS High	MOS过温保护温度			
10	Temperature	MOS Over-heating	115°C	Yes	
	Protection	Protection Temperature	113 C	105	
		MOS保护解除温度			
		MOS Protection Release	85°C	Yes	
			65 C	1 05	
		Temperature 充电低温告警温度			
			0°C	Yes	
		Charging Low Temperature	0.0	i es	
		Warning Temperature			
		充电低温保护温度	500	3 7	
		Charging Low Temperature	-5°C	Yes	
		Protection Temperature			
		充电低温保护解除温度	000	T 7	
		Charging Low Temperature	0°C	Yes	
		Protection Release			
		Temperature			
		充电高温告警温度		Yes	
		Charging High Temperature	60°C		
	电芯温度保护	Warning Temperature			
11	Battery Cell Temperature Protection	充电高温保护温度			
		Charging High Temperature	65°C	Yes	
		Protection Temperature			
		充电高温保护解除温度			
		Charging High Temperature	55°C	Yes	
		Protection Release			
		Temperature			
		放电低温告警温度			
		Discharge Low	-15°C	Yes	
		Temperature Warning			
		Temperature			
		放电低温保护温度			
		Discharge Low	-20°C	Yes	
		Temperature Protection			
		Temperature			
		放电低温保护解除温度			
		Discharge Low	-15°C	Yes	
		Temperature Protection			
		Release Temperature			



		2.1. 1. 2 \H /I. #4 \H 24			
		放电高温告警溫度			
		Discharge High	65°C	Yes	
		Temperature Warning			
	1 11.50	Temperature			
	电芯温度保护	放电高温保护温度			
	Battery Cell	Discharge High	70°C	Yes	
11	Temperature	Temperature Protection			
	Protection	Temperature			
		放电高温保护解除温度			
		Discharge High	60°C	Yes	
		Temperature Protection			
		Release Temperature			
		环境低温告警温度			
		Environment Low	-15°C	Yes	
		Temperature Warning			
		Temperature			
		环境低温保护温度			
		Environment Low	-20°C	Yes	
		Temperature Protection		100	
		Temperature Protection			
		环境低温保护解除温度			
	环境温度告警		-15°C	Yes	
12	Environment	Environment Low	-13 C	168	
	Temperature Warning	Temperature Protection			
		Release Temperature			
		环境高温告警温度	650C	N/	
		Environment High	65°C	Yes	
		Temperature Warning			
		Temperature			
		环境高温保护温度	7500	*7	
		Environment High	75°C	Yes	
		Temperature Protection			
		Temperature			
		环境高温保护解除温度	4500		
		Environment High	65°C	Yes	
		Temperature Protection			
		Release Temperature			
		.,, .,	,	带显示屏)	
	we expense	工作时自耗电电流		vith display)	
	消耗电流	Self-consumption Current	$\leq 40 \text{mA}$ (\geq	不带显示屏)	
13	Consumption	during Operation	$\leq 40 mA (with$	thout display)	
	Current	低功耗模式电流	,	1 4/	
		Low Power Mode Current	≤ 20	0 μΑ	
				•	
		均衡开启电压			
	均衡功能	Equalization Activation	3500 mV	Yes	
14	Equalization	Voltage			
	Equalization	Function 开启压差			
	1 011011011	Activation Voltage	30 mV	Yes	
		Difference	30 m v	103	
	由昙瓜生敬	电量低告警门槛			玄由时
15	电量低告警		SOC < 5%	Yes	充电时不告警
13	Low Battery	Low Battery Warning	300 < 3%	1 68	No Warning
	Warning	Threshold			during
					Charging



16	休眠功能 Sleep Function	休眠电压 Sleep Voltage	3150 mV	Yes	_
10	Sleep Function	延迟时间 Delay Time	5 min	Yes	
17	电芯失效保护 Battery Cell Failure Protection	单体压差 Single-cell Voltage Difference	压差>1V Voltage Difference	No	不允许充放电 No charging or discharging allowed.
		满充电压 Full Charge Voltage	> 56V	Yes	同时满足后停 止充电,并更
18	满充判断 Full Charge Detection	截止电流 Cut-off Current	< 2A	Yes	新SOC为 100% Once both conditions are met, stop charging and update SOC to 100%.



4.2.3 LED指示说明/LED Indication Instructions

表1 LED工作状态指示

Table 1 LED Working Status Indication

Table I LED Working Status Indication											
状态	正常/告警/保护	ON/ OFF	RUN	说的				说明			
Status	Normal/Warnin					Batter	y Level	Indicato	r LED		Explanation
	g/Protection										
关机	休眠	灭	灭	灭	灭	灭	灭	灭	灭	灭	全灭
Power off	Sleep	Off	Off	Off	Off	Off	Off	Off	Off	Off	All off
 待 <u>机</u>	正常	常亮	闪1	灭			龙 捉由	量指示			待机状态
	Normal	On	Flash	Off			•••				Standby Mode
Standb v	告警	常亮	闪1	闪3		Bas	ed on ba	ittery ind	licator		
	Warning	On	Flash 1	Flash 3						Module low voltage	
	正常	常亮	常亮	灭	灭 依据电量指示 最高电量LED闪动(闪)						最高电量LED闪动(闪2),过
	Norma1	On	On	Off		(电:	量指示	最高LEI	充告警时ALM不闪烁 Highest battery level LED		
充电	告警	常亮	常亮	闪3		В	ased on	battery i			
Charg	Warning	On	On	Flash (Highest battery level LED flashes 2) flash					flash		
ing				,	(Flash 2)					, ,	
											during overcharge warning, ALM does not blink
	过充保护	常亮	常亮	灭	常亮	常亮	常亮	常亮	常亮	常亮	若无市电,指示灯转为待机状态
	Overcharge protection	vercharge On On Off On On On On On On							On	If no mains power, indicator light switches to standby mode	
	温度、过流、失 效 保护	- ` ` 宣昌 ル 宣昌 ル ル ル ル ル ル					灭	停止充电			
	Temperature,	On	Off	On	Off Off Off Off Off Off					Stop charge	
	Overcurrent,										
	Failure Protection										



	正常 Normal	常亮 On	闪3 Flash 3	灭 Off			-	量指示			
放电 Dischar	告警	常亮	闪3	闪3			Based (on batter			
ging	Warning	On	Flash 3	Flash 3							
	欠压保护	常亮	灭	灭	灭	灭	灭	灭	灭	灭	停止放电
	Undervoltage protection	On	Off	Off	Off	Off	Off	Off	Off	Off	Stop discharge
	温度、过流、短 路、反接、失	常亮 On	灭	常亮	灭	灭	灭	灭	灭	灭	停止放电
	效保护		Off	On	Off	Off Off Off Off Off					Stop discharge
	Temperature, Overcurrent, Short circuit, Reverse connection, Failure protection										
失效		灭	灭	常亮	灭	灭	灭	灭	灭	灭	停止充、放电
Failure		Off	Off	On	Off	Off	Off	Off	Off	Off	Stop charge and discharge

表2 容量指示说明 Table 2 Capacity Indication Explanation															
状态 Stat		充电 Charging						放电 Discharging							
容量指示灯 Capacity Indicator		L6	L5	L4	L3	L2	L1	L6	L5	L4	L3	L2	L1		
	0~16.6%	灭 Off	灭 Off	灭 Off	灭 Off	灭 Off	闪2 Flashing 2	灭 Off	灭 Off	灭 Off	灭 Off	灭 Off	常亮 On		
电量(%) Battery level(%)															
	16.6~33.2%	灭 Off	灭 Off	灭 Off	灭 Off	闪2 Flashing 2	常亮 On	灭 Off	灭 Off	灭 Off	灭 Off	常亮 On	常亮 On		
	33.2~49.8%	灭 Off	灭 Off	灭 Off	闪2 Flashing 2	常亮 On	常亮 On	灭 Off	灭 Off	灭 Off	常亮 On	常亮 On	常亮 On		
	49.8~66.4%	灭 Off	灭 Off	闪2 Flashing 2	常亮 On	常亮 On	常亮 On	灭 Off	灭 Off	常亮 On	常亮 On	常亮 On	常亮 On		
	66.4~83.0%	灭 Off	闪2 Flashing 2	常亮 On	常亮 On	常亮 On	常亮 On	灭 Off	常亮 On	常亮 On	常亮 On	常亮 On	常亮 On		
	83.0~100%	闪2 Flashing 2	常亮 On	常亮 On	常亮 On	常亮 On	常亮 On	常亮 On	常亮 On	常亮 On	常亮 On	常亮 On	常亮 On		



5 包装、储存、运输/Packaging, Storage, and Transportation

5.1 包装/Packaging

- 1) 装有电池产品的包装盒应放在干燥、防尘、防潮的包装箱内。
- 2) 包装示意图
- 1) Packaging boxes containing battery products should be placed in dry, dust-proof, and moisture-proof packaging boxes.
- 2) Packaging diagram





5.2 储存/Storage

- 1) 产品应存放在干燥,通风,并能防雨,雪的室内,不应与活性化学物品或起尘物品存放在一起,箱体应放妥垫起,距地面不小于 100mm。
- 2) 产品应避免受阳光直射,离热源(暖气设备等)不应少于2m。
- 3) 产品不应倒置及卧放,不应受任何机械冲击或重压。
- 4) 电池或电池组应在荷电不超过 30%~50%的状态下以及环境温度为 5℃~35℃的条件下,进行存储或运输。
- 1) The product should be stored indoors in a dry, well-ventilated area that is protected from rain and snow. It should not be stored together with reactive chemicals or dusty materials. The product should be properly placed on a pad or raised surface, with a distance of at least 100mm from the ground.
- 2) The product should be protected from direct sunlight and kept at least 2 meters away from heat sources such as heating equipment.
- 3) The product should not be inverted or placed horizontally, and it should be protected from any mechanical shocks or heavy pressure.
- 4) Batteries or battery packs should be stored or transported in a state of charge not exceeding 30% to 50% and under ambient temperatures of 5°C to 35°C.

5.3 运输/Transportation

- 1) 在运输过程中,产品不应受到剧烈机械冲击,暴晒,雨淋,不应倒置。
- 2) 在装卸过程中,产品应轻放,严防摔掷,翻滚,重压。
- 1) During transportation, the product should not be subjected to severe mechanical shocks, prolonged exposure to sunlight, or rain. It should not be inverted.
- 2) During loading and unloading, the product should be handled with care to prevent dropping, rolling, or excessive pressure.



6 成品尺寸及接口说明/Product Dimensions and Interface Description

成品尺寸: L450*W475*H155,单位 mm,输入输出接口: M6 螺丝,橙正、黑负。

Product dimensions: L450*W475*H155 (in millimeters). Input/output interface: M6 screw, orange positive, black negative.



7 使用说明与注意事项/Instructions and Precautions

7.1 使用说明/Instructions

- 1) 使用电池前,请仔细阅读使用说明书和电池表面标识。
- 2) 请在正常的、室内环境中使用电池。温度: -20~+35℃,相对湿度: 55±20%。
- 3) 在使用过程中,应远离热源、高压,避免儿童玩弄电池。切勿摔打电池。本电池只能使用配套充电器 充电。不要将电池放在充电器中充电超过 24h。
- 4) 切勿将电池正负极短路,切勿自己拆装电池,也勿让电池受潮,以免发生危险。
- 5) 长期不用时,请将电池储存完好。让电池处于半荷电状态。请用不导电材料包裹电池,以避免金属直接接触电池,造成电池损坏。将电池保存在阴凉干燥处。
- 6) 废弃电池请安全妥当处理,不要投入火中或液体中。
- 1) Before using the battery, please read the user manual and check the surface markings of the battery.
- 2) Please use the battery in normal indoor environments. Temperature: -20 to +35°C, relative humidity: 55±20%.
- 3) During use, keep the battery away from heat sources and high voltage, and prevent children from playing with the battery. Do not drop or strike the battery. Only use the provided charger to charge the battery. Do not charge the battery in the charger for more than 24 hours.
- 4) Do not short-circuit the positive and negative terminals of the battery, and do not disassemble the battery by yourself



or let the battery get wet to avoid potential hazards.

- 5) When not in use for a long time, store the battery in a good condition. Keep the battery in a partially charged state. Wrap the battery with non-conductive material to prevent direct contact with metal, which may damage the battery. Store the battery in a cool and dry place.
- 6) Dispose of the battery properly and safely. Do not throw it into fire or liquid.

7.2 注意事项/Precautions

- 1) 请不要在强阳光爆晒的环境下使用电池,以免发热、变形、冒烟。至少避免电池性能下降、减少寿命。
- 2) 电池中装有保护电路可以避免各种意外情况的发生。不要在产生静电的场所使用电池,因为高压静电容易 损坏保护板,而导致电池工作不正常,发热、变形、冒烟或起火燃烧。
- 3) 推荐的充电温度范围是 0-45℃。在超出此范围的环境中充电有可能造成电池性能下降、减少寿命。
- 4) 在使用电池之前,请仔细阅读使用手册并经常在需要时阅读。
- 5) 请使用专用充电器和推荐的充电方式,在推荐的环境条件下给电池充电。
- 6) 在第一次使用电池时,若发现电池不整洁或有异味等不正常现象,不可继续使用电池,应将电池返回 销售商。
- 7) 儿童使用电池前,应受父母指导,并在使用中受监督是否正确。
- 8) 电池应放在孩童不能得到的位置。应避免孩童将电池从充电器取出、玩弄。
- 9) 假如皮肤或衣物接触到电池漏液,请用清水冲洗,以免造成皮肤不适。
- 10) 购买电池时,请注意销售商联络方法。以便在需要时及时与销售商取得联系,得到咨询。
- **11)** 保用期是自出厂之日起十二个月。但是,属于使用不当而非质量问题,即使在保用期内生产厂家也不会无偿更换新电池。
- **12)** 如果将电池用于其他设备,请与供应商讨论保护功能的完善性。至少应该咨询电池的大电流、快速充电、特殊应用的问题。
- 1) Please avoid using the battery in environments with strong sunlight to prevent overheating, deformation, and smoking. This can cause a decrease in performance and shorten the battery's lifespan.
- 2) Batteries with built-in protection circuits can prevent various unexpected incidents. Do not use the battery in places where static electricity is generated, as high-voltage static electricity can damage the protection circuit, resulting in abnormal battery operation, overheating, deformation, smoking, or even fire.
- 3) The recommended charging temperature range is 0-45°C. Charging the battery in environments outside this range may cause a decrease in performance and shorten its lifespan.
- 4) Before using the battery, please read the user manual carefully and refer to it whenever necessary.
- 5) Please use a dedicated charger and follow the recommended charging method to charge the battery in the recommended environmental conditions.
- 6) If you find any abnormalities such as dirtiness or unusual odor when using the battery for the first time, do not continue using it and return the battery to the retailer.
- 7) Children should be guided by parents and supervised during battery usage to ensure proper handling.
- 8) Keep the battery in a place inaccessible to children. Avoid children removing the battery from the charger and playing with it.



- 9) If skin or clothing comes into contact with battery leakage, rinse with water to prevent discomfort.
- 10) Please pay attention to the contact information of the retailer when purchasing the battery, so that you can contact them for consultation when needed.
- 11) The warranty period is twelve months from the date of purchase. However, if the battery is improperly used rather than having a quality issue, the manufacturer will not provide free replacement even within the warranty period.
- 12) If using the battery for other devices, discuss with the supplier regarding the adequacy of protection functions. At least consult about high current, fast charging, and special application issues related to the battery.

7.3 警告/Warning

- 1) 不可与其它类型的一次或二次电池混用,否则会因为不正常的充、放电造成电池发热、冒烟、变形或 燃烧。
- 2) 将电池置于孩童不能得到的地方,以避免孩童噬咬或吞咽电池。如果吞咽了电池,应迅速送医院处理。
- 3) 如果超过正常充电时间很长时间充电器仍在充电,应停止充电。不正常的充电有可能会使电池发热、 冒烟、变形或燃烧。
- 4) 不可置于微波炉或其他压力容器中,瞬间加热或结构损坏会使电池发热、冒烟、变形或燃烧。
- 5) 假如发现电池漏液(或有异味),应让电池远离火源。否则,渗漏的电解液会着火,甚至造成其它危险。
- 6) 假如发现电池有异味、变形、变色或扭曲,应让电池离开手机或充电器并弃用。使用不正常的电池会 发热、冒烟、变形或燃烧。
- 1) Do not mix the battery with other types of primary or secondary batteries. Improper charging or discharging can cause the battery to overheat, smoke, deform, or ignite.
- 2) Keep the battery out of reach of children to prevent them from biting or swallowing the battery. If a battery is swallowed, seek medical attention immediately.
- 3) If the charger continues to charge for an unusually long time beyond the normal charging duration, stop charging. Abnormal charging can cause the battery to overheat, smoke, deform, or ignite.
- 4) Do not place the battery in a microwave or other pressurized containers as sudden heating or structural damage can cause the battery to overheat, smoke, deform, or ignite.
- 5) If battery leakage is detected (or if there is an unusual odor), keep the battery away from any sources of fire. Leaking electrolyte can ignite and pose additional hazards.
- 6) If the battery shows any signs of an unusual odor, deformation, discoloration, or distortion, remove the battery from the device or charger and discontinue its use. Using an abnormal battery can result in overheating, smoking, deformation, or combustion.